

PORT OF FLEETWOOD

NOTICE to MARINERS 04 of 2025

Mariners are hereby advised:

that No 4 Buoy (VQR) in approximate position 53 deg 57.6 minutes North, 003 deg 01.63 minutes W, has been reported as missing.

Mariners are advised to navigate with caution.

ABP Fleetwood Tel 01253 879060
Port Office
Fleetwood FY7 6PP

Richard Webb
Harbour Master
22.04.2025