

PORT OF FLEETWOOD

NOTICE to MARINERS - 09 / 2025

Removal of No 7 Buoy

Mariners are advised that :

the Starboard Hand Buoy No.7, in the River Wyre, Fleetwood, has been damaged and is in need of repair.

To enable repair, the buoy has been removed and there is no temporary replacement.

It is intended that repair should take as little time as possible before re-locating to its' original position.

All mariners are advised to navigate the area with caution, especially during the hours of darkness.

For any further information please contact Fleetwood dock on vhf channel 12 during tide times.



ABP Fleetwood Tel 01253 879060

Port Office

Fleetwood FY7 6PP

Richard Webb

Div Harbour Master

25.09.2025