

Port of Fleetwood

NOTICE TO MARINERS No 20 of 2023

CHANGE OF LIGHT CHARACTERISTICS

MARINERS ARE ADVISED that the Leading Lights charted as Lower Shore Front and Upper Shore Rear were charted light character as green.

These lights have been showing white rather than Green for several years. Following consultation with Trinity House in their capacity as the General Lighthouse Authority, it has been agreed to amend the publications that refer to these lights rather than the characteristics of the physical lights.

Summary of the changes

AtoN No	Aid To Navigation	Position	Aid Type	Change
N03487	Lower Shore Front	53° 55.712' N 003° 00.544' W	Leading Light	Light Character charted as Green - - Showing a white light.
N03488	Upper Shore Rear	53° 55.589' N 003° 00.452' W	Leading Light	Light Character charted as Green - - Showing a white light.

All mariners are advised to amend any charts, publications and passage plans to reflect these changes.

For any further information please contact Fleetwood dock on vhf channel 12 during tide times.

Steve Hearn
Marine Manager
14th NOVEMBER 2023